


	5C	outh		ROPRIETARY ITEM - EXCEPT FOR USE RANTED IN WRITING INFORMATION DI EREON IS CONFIDENTIAL AND ALL RI ND OTHERWISE ARE RESERVED BY SOU	S EXPRESSLY SCLOSED GHTS PATENT THCO, INC.	No. 50 RESS-	6 SPRING -IN STYLE	LOADED P W SMALL	LUNGER ASSE OVERMOLDED	MBLY KNOB	DATE 29APRIL2003	DRAWN MJS	CHKD LL	SCALE NTS	TD-56-16	X-J
RE	EΥ	DATE	DRAWN/CHKE	DESCRIPTION												\wedge
																PAPER
					1										THIRD ANGLE PROJECTION	

SOUTHCO PERFORMANCE GUIDELINES

THE PERFORMANCE GUIDELINES SHOWN ON THIS PAGE ARE SUPPLIED AS A GENERAL GUIDE ONLY, AS CONDITIONS VARY WITH EACH APPLICATION AND METHOD OF INSTALLATION. STRENGTH DATA GIVEN IS FOR FAILURE OF THE PRODUCT OR FOR SUFFICIENT DEFORMATION TO MAKE PRODUCT INOPERABLE, NO SAFETY FACTOR HAS BEEN APPLIED IT IS RECOMMENDED 1THAT THE USER REQUEST A PRODUCT SAMPLE FOR TESTING TO DETERMINE THE SUITABILITY OF THE PRODUCT FOR THE PURPOSE INTENDED AND USER'S PARTICULAR APPLICATION.









INSTALLATION

PUSH-OUT

SIDE LOAD (Assembly shown: 56-161-000)

SHEAR

ASSEMBLY PART NUMBERS	PANEL MATERIAL	OPTIMUM Installation force		MINIMUM PUSH-OUT FORCE HELD				NIMUM SIE DRCE HELE		MINIMUM ULTIMATE SHEAR LOAD		
		N	lbf.	N	lbf.	Failure Mode	N	lbf.	Failure Mode	N	lbf.	Failure Mode
56-16X-EEE	(1)	6,700	1,506	1,500	337	А	530	119	А	N/A	N/A	N/A
	(2)	13,400	3,012	1,780	400	А	290	65	А	N/A	N/A	N/A
	(3)	N/A	N/A	N/A	N/A	N/A	N/A	N/A	N/A	5,600	1,258	В

Salt Spray Test Data: Parts passed 500 hours of salt spray testing exposure per ASTM B-117.

No visual rust observed; no loss of function.

- 1. Assemblies were installed and tested in 1.6mm (.060 inches) thick 5052-H32 Aluminum panels.
- 2. Assemblies were installed and tested in 1.6mm (.060 inches) thick ASTM A109 TEMPER 2 Steel panels (55-70 HRB).
- 3. Assemblies were installed and tested in 1.7mm (.065 inches) thick hardened steel panels (61 RB).

FAILURE MODES OBSERVED IN TESTING:

- A. Ferrule push out of panel or the ferrule flange broke away from the main part of the ferrule.
- B. Excessive panel deformation and stud broken.

REF: 56-40